Partition Transfer Grille

No Scale   Detail 40

Grille located high in wall on
bedroom side to prevent
blocking by furniture

Cavity wall is sealed tight,
drywall glued to studs and
plates on both sides

Grille located low in wall on
hallway side